Johns Creek Stream Restoration Buffer Variance Request Photos Page





Photograph 1: Downstream end of buffer and greenway at East Johns Crossing, facing northeast.

Photograph 2: Downstream end of buffer and greenway at East Johns Crossing, facing south.





Photograph 3: Buffer and greenway at southeasternmost parcel, facing northeast.



Photograph 4: Buffer and greenway at southeasternmost parcel, facing northeast.





Photograph 5: Buffer and greenway at the northwest corner of the southeastern-most parcel, facing northeast.



Photograph 6: Buffer and greenway just south of an existing pedestrian footbridge, facing northeast.






Photograph 7: Buffer at existing pedestrian footbridge, facing northeast.



Photograph 8: Existing pedestrian bridge crossing Johns Creek, facing west.









Photograph 10: Buffer and greenway north of existing pedestrian access to parking lot on the east, facing northeast.





Photograph 11: Buffer and greenway at east central parcel where greenway is temporarily closed for public safety, facing northeast.



Photograph 12: Upstream end of buffer and greenway at northeastern parcel, facing northeast. Note: this parcel is not part of the buffer variance request.

